


FPSO STEEL RENEWALS PROJECT

No Dry Dock – Safely

By


Peter Gresty

Project Manager & Manager QHSE



PROJECT SCOPE

- The scope originated from the outstanding Recommendations from the ABS continuous survey
 - There were a total of 33 Outstanding Recommendations
 - EM&I were contracted to review the scope and to provide specialist repair and inspection services





PROJECT SCOPE

- Ballast Tank Repairs
- Sea Chest Repairs
- Engine Room Repairs
- Deck Penetration Repairs



EM&I PROJECT RESPONSIBILITIES

- Project Management
- Safety Supervision
- Class Liaison
- Naval Architect Services
- Repair Methodology
- Inspection Services
- Rope Access Services
- Drawing Preparation
- Planning
- Documentation
- Personnel Resources



PROJECT PREPARATION

- Pre-Mobilisation Site Visit
 - Safety Management System
 - Access & Lifting Plan
 - Tank Preparation Plan
 - Equipment Requirements
 - Operational Issues
 - Manning Levels
 - Timelines
 - Approvals – Class, Operator, NOC

DOCUMENTATION

- Project Manual
- HSE Plan
- Quality / Audit Plan
- Work Packs
- Cutting Plans
- Steel Weight Calculations
- CTRs
- Project Timelines
- Timesheets
- Risk Register
- Repair Drawings
- Equipment Manifests
- Inspection Reports
- Daily Progress Reports
- Rigging Plans
- Certification / Approvals
- Budget vs Actual Reports
- Close-out Reports



PROJECT MANAGEMENT

- Appoint Project Team
- Kick-off Meeting
- Review Stakeholders' Objectives
- Agree Workscope
- Agree Interfaces (HSE, Ops, Maintenance, Onshore, Class etc)
- Review Data/Document Requirements
- Develop Project Manual, HSE Plan, Quality Plan, Comms Plan etc
- Select & Brief Site Team

PROJECT MANAGEMENT

- Visa, Work Permits, Customs
- Mobilise Equipment & Site Team
- Daily Site Team Briefings, Toolbox Talks etc
- Daily Progress Reports
- Variation Orders
- Data Collection
- Documentation, Approvals, Certification etc
- Close-out & Lessons Learned


ENGINEERING SPECIFICATION

- Steel Renewal Survey
 - Class Surveyor in attendance
- Structural Assessment – Naval Architect
- Work Pack Development
 - Drawings
 - Welding Procedures
 - Steel Weight Calculations
 - Hot Work Habitat Procedure
 - Inspection Requirements



PROJECT INNOVATION

- Manpower Coordination
 - Split Shifts, Site Safety Management, Language
- Working Environment Challenges
 - Working within Confined Space
 - Lifting and Rigging Operations
 - Structural Integrity during repairs
 - Sea State, weather conditions
 - Accommodation Vessel



PROJECT INNOVATION

- Repair Methodology
 - Side Shell Impact Damage – re-engineer repair methodology to avoid crop and renew below the water line
- Welding Practices and Equipment
 - Flux Cored Arc Welding versus Conventional MMAW Procedures
- Material Handling
 - Steel plating and stiffening elements
 - Utilities – Generators, Compressors, Welding Machines
 - Ventilation Equipment

PROJECT STATISTICS

■ Total Offshore Manhours

- Port Auxiliary Sea Chest 1,819 hours
- No. 1 Port and No.1 Starboard WBT 172,845 hours
- No. 3 Starboard WBT 122,127 hours
- Deck Repairs & Penetrations 80,000 hours

■ Total Steel Tonnage


- No.1 Port and No.1 Starboard WBT 88 tonnes
- No. 3 Starboard WBT 68 tonnes
- Deck Penetration Repairs – Including replacement of 106 Butterworth hatches, stub piping, level alarms, manholes. 4 Tonnes

Key Performance Indicators

- Safety Management Performance
- Impact or interruption to production
- Project delivered to maximise local manpower content
- Transfer of technology for Inspection, Repairs and Maintenance (IRM) projects to local partners
- Further development of IRM management systems for local projects

PROJECT SCOPE

- Water Ballast Tank Repairs
 - No.1 Port Water Ballast Tank
 - No.1 Starboard Water Ballast Tank
 - No.3 Starboard Water Ballast Tank



Fi.76

Fi.77


Fi.78

Fi.79

Fi.80

Fi.81

Fi.82



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity





FPSO REPAIR PROJECT

EM&I
Delivering Integrity

Delivering Integrity



FPSO REPAIR PROJECT

EM&I


Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



PROJECT SCOPE

- Sea Chest Repairs
 - Auxiliary Sea Chest Port
 - High Sea Chest Starboard

FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity




PROJECT SCOPE

- Deck Repairs

FPSO REPAIR PROJECT

EM&I


Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



FPSO REPAIR PROJECT

EM&I

Delivering Integrity



PROJECT SCOPE

- Engine Room Structural Renewals

FPSO REPAIR PROJECT

EM&I

Delivering Integrity



SUMMARY

- Over 380,000 manhours without injury of any sort
- 160 Tonnes of Steel replaced
- Work carried out on station
- No production downtime
- No disruption to offload schedule
- Maximised local content
- Technology transfer/knowledge sharing to local company
- Reduced repair scope
- Completed to agreed timescales and within budget

Any Questions

?

The logo for EM&I, featuring the letters 'EM&I' in a bold, yellow, sans-serif font. The letters are contained within a blue rounded rectangle with a slight gradient. The background of the entire page is a photograph of an offshore oil rig at sunset, with a large yellow and blue curved graphic element at the top.

EM&I

Delivering Integrity

www.emiall.com